

## **GeoMoS Orientation Procedure**

This document outlines how to orientate the total station using the "Sensor Location Editor" in GeoMoS Monitor version 6.3.

 Select the "Configuration" tab from the top menu and choose "Sensor location editor" from the list of options. You will see the screen below which shows all sensors that are configured in GeoMoS. You must select the instrument that you wish to orientate and then click the "Orientation" button on the right. NOTE: Before starting this process, please ensure that the instrument that you are orientating in the field is pointed at its reference prism and has it's Azimuth (horizontal angle) set to 0°0'0".

Se	ensor Location	and includes			? ×
	Name INSTRUMENT 1 WXT520	Point ID PILLAR 1 PILLAR 1	Type TM50/TS50/MS50 Vaisala WXT520	Descriptic	OK Cancel Setup Orientation Properties
	•			4	

2. Click "Next" on the first screen shown below.

Orientation Step 1 of 4	? <mark>×</mark>
Stand Point	
Point: PILLAR 1 Date / Time: 08.03.2016 10:48:03	TPS-Sensor INSTRUMENT 1
< Back Finish	Next > Cancel

3. Enter the height of the instrument (shown as Meters) which is the height of the middle of the telescope from the top of the pillar. This is typically 0.245m but add an additional 0.005m if the aluminium instrument housing is installed. Click "Next".

Orientation Step 2 of 4						
Enter the instrument height and orientation manually. Press "Finish" to end or "Next" to calculate the orientation by measuring to a point.						
Instrument height:	0.245	] m				
Orientation:	0° 0′ 0.0000″	]				
< Back Next > Finish Cancel						

4. Select the point (Reference prism) that the instrument is pointed at then select next.

Orientation Step 3 of 4						
Target po	oint selection:					
Point:	REF 1					
	< Back Next > Finish Cancel					

5. Ensure that the check box to use the "ATR" is ticked and click "Measure".

Orientation Step 4 of 4							
Point to the reflector and press the measure button. The Orientation will be automatically calculated.							
Orientation:	0° 0′ 0.0000″						
🔽 Use ATR	Measure						
< Ba	ck Next >						
Finish Cancel							

6. The value shown for orientation should now change to the true bearing and you can select "finish" to complete the process.